

CLEANER AC

Cement slush remover



CHARACTERISTICS



+30 °C

+15 °C

CLEANER AC is a very powerful cement film remover and cleaning agent. It removes lime and cement films from almost all surfaces such as tiles, facade bricks, garage driveways, and terraces. CLEANER AC can also be used for descaling tile walls, bathtubs, faucets, etc.

1. A powerful acid cleaner with excellent cleaning properties on many surfaces.
2. It contains no hydrochloric acid.
3. Consumption of 950 ml CLEANER AC for approximately 20 to 30 m² with normal contamination. The consumption depends on the condition of the surface.

Mixing ratio	Consumption	Package
Light soiling: 1/3 (product/water) Heavy soiling: 1/1 (product/water) or pure	950 ml for approx. 20 to 30 m ² with normal soiling (depending on the condition of the surface).	950 ml (20 pc/carton)
Color	Processing time	Operating temperature
Colourless	±5 to 20 min.	+15 °C to +30 °C

CLEANER AC

DIRECTIONS OF USE

Thoroughly dampen the surface, then dilute CLEANER AC with water. The dilution ratio depends on the degree of soiling. Light soiling: dilute 1 part of the product with 3 parts water. Heavy soiling: 950 ml of water for 950 ml of CLEANER AC or use pure.

Apply CLEANER AC with a brush. Do not cover more than 10 to 15 m² at a time. Recommended reaction time: allow it to work for 5 to 20 minutes, depending on the degree of contamination. During the reaction time, keep the floor damp with the diluted CLEANER AC solution. Afterward, rinse thoroughly with water, and use a brush if necessary. If unsure about the acid resistance of the material being cleaned, test for acid sensitivity in an inconspicuous area beforehand.

REMARKS

- Do not use on acid-sensitive materials such as marble, certain natural stones, and highly calcareous tiles, as well as colored plastics, galvanized, and zinc-coated surfaces.
- Do not use on calcareous building materials such as cement and granito floors, cement-masticated building materials, some paints, etc.
- Test on non-ferrous metals beforehand.
- Store in a frost-free place.

SAFETY PRECAUTIONS

Wear gloves and safety goggles when working with CLEANER AC. Avoid inhaling fumes. Never mix with other cleaning agents. Carefully read the safety instructions on the packaging. Request the safety data sheet.

