

AEROFLEET CATAMARAN

Belgium



Problem

Salt water, moisture, salty air.

Surface outside: polyester.

Surface inside: polyester and wood.

Solution

- Pre-treatment: degrease thoroughly, carefully sand
- System - outside of the boat:
Cryltane DTS 20 + Mixtane High Gloss
- System - inside of the boat: **Cryltane DTS 20 + Mixtane**
(multiple glosses).

